

# ENGINEERING DRAWING

## FROM THE BEGINNING

M.F. Cousins

VOLUME 2



THE COMMONWEALTH AND INTERNATIONAL LIBRARY

*Joint Chairmen of the Honorary Editorial Advisory Board*

SIR ROBERT ROBINSON, O.M., F.R.S., LONDON

DEAN ATHELSTAN SPILHAUS, MINNESOTA

---

MECHANICAL ENGINEERING DIVISION

*General Editor: N. HILLER*

---

***Engineering Drawing from the Beginning***

VOLUME 2

This page intentionally left blank

# *Engineering Drawing from the Beginning*

VOLUME 2

*by*

M. F. COUSINS

UNTIL RECENTLY CHIEF DESIGNER, CAMBRIDGE INSTRUMENT CO. LTD.

DESIGN CONSULTANT

PART-TIME LECTURER IN ENGINEERING DRAWING,

CAMBRIDGESHIRE COLLEGE OF ARTS AND TECHNOLOGY



PERGAMON PRESS

OXFORD · LONDON · EDINBURGH · NEW YORK  
TORONTO · SYDNEY · PARIS · BRAUNSCHWEIG



Pergamon Press Ltd., Headington Hill Hall, Oxford  
4 & 5 Fitzroy Square, London W.1  
Pergamon Press (Scotland) Ltd., 2 & 3 Teviot Place, Edinburgh 1  
Pergamon Press Inc., Maxwell House, Fairview Park, Elmsford, New York 10523  
Pergamon of Canada Ltd. 207 Queen's Quay West, Toronto 1  
Pergamon Press (Aust.) Pty. Ltd., 19a Boundary Street,  
Rushcutters Bay, N.S.W. 2011, Australia  
Pergamon Press S.A.R.L., 24 rue des Écoles, Paris 5<sup>e</sup>  
Vieweg & Sohn GmbH, Burgplatz 1, Braunschweig

---

Copyright © 1970 M. F. Cousins

First edition 1970

*All Rights Reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording or otherwise, without the prior permission of Pergamon Press Ltd.*

Library of Congress Catalog Card No. 63-22313

---

*Printed in Great Britain by A. Wheaton & Co., Exeter*

This book is sold subject to the condition  
that it shall not, by way of trade, be lent,  
resold, hired out, or otherwise disposed  
of without the publisher's consent.  
in any form of binding or cover  
other than that in which  
it is published.

**08 006854 5 (Hard Cover Non Net)**

**08 006853 7 (Hard Cover)**

# Contents

---

LIST OF ILLUSTRATIONS	xi
EDITOR'S PREFACE	xxi
AUTHOR'S ACKNOWLEDGEMENTS	xxiii
<b>1 Revision and Introduction</b>	<b>1</b>
1.1 <i>Revision of Previous Work from Volume 1</i>	1
1.2 <i>Types of Projection</i>	1
1.3 <i>Dimensioning</i>	1
1.4 <i>Sectional Views</i>	1
1.5 <i>Part or Detail Drawing</i>	1
1.6 <i>Assembly Drawing</i>	4
1.7 <i>Sub-assemblies</i>	4
1.8 <i>Division of a Line into Equal Parts</i>	4
1.9 <i>Joining of Straight Lines to Curves</i>	4
1.10 <i>Pencil Point</i>	4
1.11 <i>Division of Circumference of a Circle</i>	4
1.12 <i>Radius Corners</i>	4
<b>2 The Helix</b>	<b>7</b>
2.1 <i>Definition of the Helix</i>	7
2.2 <i>The Construction of a Helix</i>	7
2.3 <i>The Construction of a Double Helix</i>	9
2.4 <i>The Construction of a Helical Groove in a Cylinder</i>	9
2.5 <i>A Helical Spring (Round Wire)</i>	9
2.6 <i>A Square Thread</i>	12
2.7 <i>A Helical Spring (Square Wire)</i>	12
2.8 <i>The Ellipse</i>	15
<b>3 Interpenetration of Solids</b>	<b>22</b>
3.1 <i>Simple Rectangular Objects</i>	22
3.2 <i>Hexagonal Prisms</i>	22
3.3 <i>Square Pyramids</i>	25
3.4 <i>Auxiliary Views and True Shapes</i>	30
3.5 <i>Hexagonal Prisms</i>	32
3.6 <i>Hexagonal Pyramids</i>	32
3.7 <i>Cylinders</i>	37
3.8 <i>Cones</i>	42
<b>4 Development</b>	<b>48</b>
4.1 <i>Cylinder</i>	48
4.2 <i>Cube</i>	48
4.3 <i>Rectangular Object</i>	51
4.4 <i>Hexagonal Object</i>	51

4.5	<i>Cube (Cut)</i>	51
4.6	<i>Square Pyramid</i>	51
4.7	<i>Square Pyramid (Cut)</i>	56
4.8	<i>Square Pyramid (Double Cut)</i>	56
4.9	<i>Cylinder (Cut)</i>	59
4.10	<i>Cylinder (Cut)</i>	61
4.11	<i>Elbow, 90°</i>	61
4.12	<i>T with Equal Diameter Pipes</i>	64
4.13	<i>T with Unequal Diameter Pipes</i>	67
4.14	<i>45° Angle T</i>	67
4.15	<i>Branch T. Development of Pipes of Unequal Diameters</i>	72
4.16	<i>Branch T. Development of Pipes of Unequal Diameters</i>	74
4.17	<i>Offset T. Complete Development</i>	74
4.18	<i>Cone Development</i>	74
4.19	<i>Cone (Cut). Development</i>	78
4.20	<i>Cone (Double Cut). Complete Development</i>	78
4.21	<i>Cone (Cut). Development of Curved Surface Only</i>	82
<b>5</b>	<b>Conventional Representations of Common Features</b>	<b>83</b>
	EXTRACTS FROM B.S. 308	
5.1	<i>Screw Threads</i>	83
5.2	<i>Springs, Compression</i>	83
5.3	<i>Springs, Tension</i>	83
5.4	<i>Knurling</i>	83
5.5	<i>Hexagon Nut</i>	83
5.6	<i>Hexagon Bolt</i>	86
5.7	<i>Square End on Shaft</i>	86
5.8	<i>Holes on a Circular Pitch</i>	86
5.9	<i>Holes on a Linear Pitch</i>	86
5.10	<i>Bearings</i>	86
5.11	<i>Round Rod</i>	86
5.12	<i>Round Tube</i>	86
5.13	<i>Rectangular Bar (Metal)</i>	86
5.14	<i>Rectangular Bar (Wood)</i>	89
<b>6</b>	<b>Fastenings</b>	<b>90</b>
6.1	<i>Riveting</i>	90
6.2	<i>Lap Joints</i>	92
6.3	<i>Butt Joint. Single Cover Plate</i>	92
6.4	<i>Butt Joint. Double Cover Plate</i>	92
6.5	<i>Angle-riveted Joint</i>	92
6.6	<i>Angle-riveted Joint</i>	92
6.7	<i>Built-up Girder</i>	92
6.8	<i>Built-up Box Girder</i>	92
6.9	<i>Taper Keys</i>	96
6.10	<i>Parallel Keys</i>	96
6.11	<i>Feather Key</i>	96
6.12	<i>Woodruff Key</i>	96
6.13	<i>Gib Head</i>	96
6.14	<i>Cotter</i>	96
6.15	<i>Butt Weld</i>	96
6.16	<i>Lap Weld</i>	96

6.17	<i>Fillet Weld</i>	98
6.18	<i>Seam Weld</i>	98
6.19	<i>Drawing Welded Joints</i>	98
6.20	<i>Lock Nut</i>	98
6.21	<i>Nuts Pinned</i>	98
6.22	<i>Sawn Nut</i>	100
6.23	<i>Spring Washers</i>	100
6.24	<i>Two Plates Clamped</i>	100
6.25	<i>Cable Clamp</i>	100
6.26	<i>Mounted Plates</i>	100
6.27	<i>Clamped Plates</i>	100
6.28	<i>Multiple Plates</i>	102
6.29	<i>Multiple Plates with Spacers</i>	102
6.30	<i>Shaft Location</i>	102
6.31	<i>Gear Reduction Unit Assembly</i>	102
6.32	<i>Screwed fitting Metal Lamp Holder</i>	102
6.33	<i>Simple Sliding Platform</i>	102
6.34	<i>Captive Screw</i>	105
6.35	<i>Packing Gland</i>	105
<b>7</b>	<b>Metrication in the Drawing Office. Limits, Fits, and Tolerances</b>	<b>106</b>
7.1	<i>Metrication</i>	106
7.2	<i>Machined Surfaces</i>	107
7.3	<i>Definition of Terms</i>	107
7.4	<i>Types of Fits</i>	107
7.5	<i>Crank Shaft Assembly</i>	111
7.6	<i>Crank Shaft. Part No. 1</i>	111
7.7	<i>Connecting Rod. Part No. 2</i>	111
7.8	<i>Bearing Bracket. Part No. 3</i>	111
7.9	<i>Bearing Cap. Part No. 4</i>	111
<b>8</b>	<b>Working Drawings</b>	<b>114</b>
8.1	<i>Gear Casing</i>	114
8.2	<i>Assignment A. Gear Casing</i>	114
8.3	<i>Assignment B. Gear Casing</i>	116
8.4	<i>Sole Plate</i>	116
8.5	<i>Assignment A. Sole Plate</i>	116
8.6	<i>Wall Bracket</i>	116
8.7	<i>Assignment B. Wall Bracket</i>	118
8.8	<i>Drillhead Bracket</i>	118
8.9	<i>Assignment A. Drillhead Bracket</i>	118
8.10	<i>Valve Case</i>	118
8.11	<i>Assignment. Valve Case</i>	118
8.12	<i>Stuffing Box Assembly</i>	120
8.13	<i>Assignment. Stuffing Box</i>	120
8.14	<i>Assignment. Screwed Flange</i>	120
8.15	<i>Assignment. Stop-valve Body</i>	120
8.16	<i>Angle Cross-Pipe Joint</i>	120
8.17	<i>Assignment. Pipe Joint</i>	123
8.18	<i>Tilting Platform</i>	123
8.19	<i>Assignment A. Tilting Platform</i>	124
8.20	<i>Assignment B. Tilting Platform</i>	124



8.21	<i>Tilting Platform. Part Drawings</i>	124
8.22	<i>Upper Platform</i>	124
8.23	<i>Spindle</i>	124
8.24	<i>Base Bracket</i>	124
8.25	<i>Bracket Bearing</i>	126
8.26	<i>Assignment A. Bracket Bearing</i>	126
8.27	<i>Assignment B. Bracket Bearing</i>	126
8.28	<i>Assignment C. Bracket Bearing</i>	126
8.29	<i>Bell Crank Lever</i>	128
8.30	<i>Assignment A. Bell Crank Lever</i>	128
8.31	<i>Assignment B. Bell Crank Lever</i>	128
8.32	<i>Overhung Crank</i>	128
8.33	<i>Assignment. Overhung Crank</i>	128
8.34	<i>Spindle Bearing Assembly</i>	128
8.35	<i>Assignment. Spindle Bearing Assembly</i>	131
8.36	<i>Spindle Bearing. Part Drawings</i>	131
8.37	<i>Assignment. Spindle Bearing</i>	131
8.38	<i>Right-angle Drive Assembly</i>	131
8.39	<i>Assignment. Right-angle Drive Assembly</i>	134
8.40	<i>Lathe Face Plate</i>	134
8.41	<i>Assignment. Lathe Face Plate</i>	134
8.42	<i>Fast and Loose Pulley Assembly</i>	136
8.43	<i>Assignment. Fast and Loose Pulley Assembly</i>	136
8.44	<i>Universal Coupling Assembly</i>	136
8.45	<i>Assignment. Universal Coupling Assembly</i>	136
8.46	<i>Simple Screw Jack</i>	138
8.47	<i>Assignment. Simple Screw Jack</i>	138
8.48	<i>Footstep Bearing</i>	138
8.49	<i>Assignment. Footstep Bearing</i>	138
8.50	<i>Pedestal Bearing Assembly</i>	138
8.51	<i>Assignment. Pedestal Bearing Assembly</i>	138
8.52	<i>Pulley Bearing Assembly</i>	140
8.53	<i>Assignment. Pulley Bearing Assembly</i>	140
8.54	<i>Part Drawings for Overhung Crank</i>	140
8.55	<i>Assignment. Part Drawings for Overhung Crank</i>	140
8.56	<i>Part Drawings of Gear Box for Right-angle Drive</i>	143
8.57	<i>Assignment. Gearbox</i>	143
8.58	<i>Assignment A. Bell Crank Lever</i>	143
8.59	<i>Assignment B. Bell Crank Lever</i>	143
8.60	<i>Assignment. Part Drawings for Pulley Bearing Assembly</i>	143
8.61	<i>Assignment. Part Drawings for Right-angle Drive</i>	147
8.62	<i>Assignment. Bearing Bracket</i>	147
8.63	<i>Wall Box</i>	150
8.64	<i>Assignment. Wall Box</i>	150
8.65	<i>Assignment. Fast and Loose Pulleys</i>	150
8.66	<i>Part Drawings for Stuffing Box Assembly</i>	150
8.67	<i>Spindle Bearing. Frame</i>	150
8.68	<i>Assignment. Part Drawing of Spindle Bearing Frame</i>	154
8.69	<i>Assignment. Main Bracket</i>	154
8.70	<i>Assignment. Part Drawings for Universal Coupling</i>	154
8.71	<i>Assignment. Part Drawings for Footstep Bearing</i>	157
8.72	<i>Assignment. Part Drawings for Pedestal Bearing Assembly</i>	157

## CONTENTS

ix

8.73	<i>Assignment. Part Drawings for Simple Screw Jack</i>	160
8.74	<i>Bearing Bracket Assembly</i>	160
8.75	<i>Offset Lens Mount Assembly</i>	163
8.76	<i>Assignment A. Assembly Drawings for Offset Lens Mount</i>	163
8.77	<i>Assignment B. Detail Drawings for Offset Lens Mount</i>	163
8.78	<i>Assignment C. Isometric View of Offset Lens Mount</i>	163
8.79	<i>Bearing Bracket Assembly</i>	163
8.80	<i>Assignment A. Assembly Drawings for Bearing Bracket</i>	163
8.81	<i>Assignment B. Detail Drawings for Bearing Bracket</i>	167
8.82	<i>Assignment C. Isometric view of Bearing Bracket</i>	167
8.83	<i>Flanged Offset T Assembly</i>	167
8.84	<i>Assignment A. Assembly Drawings for Flanged Offset T</i>	167
8.85	<i>Assignment B. Detail Drawings for Flanged Offset T</i>	167
8.86	<i>Assignment C. Isometric View of Flanged Offset T</i>	167